

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/26	MAKE	HITACHI	MODEL	ZX330LC-5B
SERIAL	HCMDDDA1P00070279			STAMP	HCMDDDA1P00070279
HR METER	15996	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	800G

ENGINE : MODEL		S/N		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR • Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE		COMMENT	
Sound	FAIR • Attn				
Oil	FAIR • Attn				
Exhaust Color	FAIR • Attn				
US EPA	YES • NO				
MAIN PUMP				BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Sound	FAIR • Attn			Lever	LONG • WRIST
Oil leakage	FAIR • Attn			Multi	MULTI • 2 • NO
Power	FAIR • Attn			ARM-CRANE	YES • NO
COOLING SYSTEM				BLADE	YES • NO
Radiator	FAIR • Attn			OFFSET	YES • NO
Oil Cooler	FAIR • Attn			OFFSET Cylinder	FAIR • Attn
OPERATING SYSTEM				Piping	YES • NO Breaker only • Multi
Swing	FAIR • Attn	ガタあり SWING: LOOSE		COMMENT	
Travel	FAIR • Attn			底板欠 SOME UNDER COVERS: MISSING	
INTERIOR See Photos. 写真参照				ブーム背面ホースひび割れあり SOME HOSES AROUND BOOM: CRACKED	
INTERIOR COND.	CLEAN • FAIR • DIRTY			リペイントあり REPAINTED	
Operator's Seat	FAIR • Attn	穴あり HOLES		バックカメラ不良 BACK MONITOR: MALFUNCTION	
Glasses	FAIR • Attn				
AirCon	A/C • H/C • H only • C only • None				
BOOM / ARM / BKT					
Boom	FAIR • Attn				
Boom Cylinder	FAIR • Attn	右側塗料付着あり RIGHT CYLINDER: PAINTY			
Arm	FAIR • Attn	ガタ大 MUCH LOOSE			
Arm Cylinder	FAIR • Attn				
ATTACHMENT	FAIR • Attn				
BKT Cylinder	FAIR • Attn			RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
				3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。