

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/23	MAKE	KATO	MODEL	HD308US
SERIAL	KWJ86701PA0006199		STAMP	6199	
HR METER	2683	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	穴あり HOLES
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	油漏れあり OIL LEAKING
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())		
Lever	LONG	• (WRIST)	
Multi	MULTI	• 2 • (NO)	
ARM-CRANE	YES	• (NO)	
BLADE	(YES)	• NO	
OFFSET	YES	• (NO)	
OFFSET Cylinder	FAIR	▪ Attn	
Piping	(YES) • NO	Breaker only ▪ (Multi)	
COMMENT			
CAB下油漏れあり BOTTOM OF CAB: OIL LEAKING			
モニター不良 MONITOR: MALFUNCTION			
！マーク表示あり WARNING LAMP: ON			
動作音(油圧がかかる音)大きい HYDRAULIC WHINING: NOISY			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。