

INSPECTION SHEET 検品書
ASPHALT FINISHER アスファルトフィニッシャー

| | | | | | | | |
|-----------------|-----------|-------------|---------|----|------------------|------------|----|
| INSPECTION DATE | 2026/1/20 | MAKE | NIIGATA | | MODEL | NFB60CVKBZ | |
| SERIAL | NFB6C0508 | | | | STAMP | NOT FOUND | |
| HR METER | 3049 | | | HR | YEAR | YR | |
| SHOE | 300G PADS | TIRE (REAR) | | | MAX PAVING WIDTH | 6000 | mm |

| ENGINE : MODEL | | | S/N | | | UNDERCARRIAGE : See Photos. 写真参照 | | |
|------------------|------|------|----------|--------|--------|----------------------------------------------------------------------|---------------------------|----|
| Oil leakage | FAIR | Attn | | | | RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 3 |
| Blow-By | FAIR | Attn | A LITTLE | MIDDLE | SEVERE | TIRE WEAR | FAIR • WORN • UNEVEN WEAR | |
| Sound | FAIR | Attn | | | | COMMENT | | |
| Oil | FAIR | Attn | | | | バッテリーランプ点灯あり BATTERY WARNING LAMP: ON | | |
| Exhaust Color | FAIR | Attn | | | | パーキングS/W不良 PARKING SWITCH: MALFUNCTION | | |
| US EPA | YES | NO | | | | SCREED WIDTH | | |
| OPERATION PUMP | | | | | | | | |
| Sound | FAIR | Attn | | | | MAIN SCREED | 2.6 | m |
| Oil leakage | FAIR | Attn | | | | WITH AUTO-WIDENER | 6.0 | m |
| Power | FAIR | Attn | | | | WITH EXTENSION | | m |
| COOLING SYSTEM | | | | | | | | |
| Radiator | FAIR | Attn | | | | LEVEL SENSOR | YES | NO |
| Oil Cooler | FAIR | Attn | | | | COMMENT | | |
| OPERATING SYSTEM | | | | | | | | |
| TRAVEL | FAIR | Attn | *1 | | | スクリード、ホッパーなどを動作すると本体後方が浮き上がる、 | | |
| SCREED(R) | FAIR | Attn | *2 | | | 動作を止めると戻る | | |
| SCREED(L) | FAIR | Attn | *2 | | | REAR PART OF BODY: | | |
| VIBRATION | FAIR | Attn | *3 | | | LIFTING UP DURING OPERATING SCREEDS, HOPPER, or SOMETHING | | |
| TAMPER | FAIR | Attn | *3 | | | (COMING BACK WHEN STOPPING TO OPERATE THEM) | | |
| SPREADER(R) | FAIR | Attn | *3 | | | スクリード上下できない(スクリードが上がらないため走行不可) | | |
| SPREADER(L) | FAIR | Attn | *3 | | | SCREEDS: UNABLE TO RAISE or LOWER (UNABLE TO TRAVEL) | | |
| HOPPER(R) | FAIR | Attn | | | | *1 調速ダイヤル不良 TRAVEL SPEED CONTROL KNOB: MALFUNCTION | | |
| HOPPER(L) | FAIR | Attn | | | | *2 シリンダー傷、メッキ剥がれ、にじみあり | | |
| FEEDER | FAIR | Attn | *3 | | | *2 CYLINDER: SCRATCHED, COATING PEELED, OIL Oozing | | |
| | | | | | | *3 動作しない NOT WORKING | | |
| | | | | | | RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。