

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/19	MAKE	KOMATSU	MODEL	PC78US-8
SERIAL	19980		STAMP	KMTPC213V01019980	
HR METER	3462	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		4D95LE-5	S/N	540062
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE :		See Photos.	写真参照
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())		
Lever	LONG ▪	(WRIST)	
Multi	MULTI ▪ 2	(NO)	
ARM-CRANE	(YES) ▪ NO		
BLADE	(YES) ▪ NO		
OFFSET	YES ▪ (NO)		
OFFSET Cylinder	FAIR ▪ Attn		
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)	*1
COMMENT			
「ドア閉めると開かなくなる可能性あり」注意記載あり			
W/NOTE OF			
“POSSIBILITY OF NOT OPENING THE DOOR IF SHUTTING THE DOOR”			
リペイントあり REPAINTED			
*1 右側繋がっていない RIGHT PIPE: NOT CONNECTING TO THE HOSE			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。