

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

| | | | | | | | | | |
|----------------------------------|---------------------------------------|------|----------------------------|--|---|---------------------------------------|---|-----------|--|
| INSPECTION DATE | 2026/1/23 | | MAKE | SUMITOMO | | MODEL | SCX550-C | | |
| SERIAL No. | PLATE : HCM24T00P00002414 | | | STAMP | 100P00002414 | | | | |
| HR METER | 18952 | HR | SHOE | 760FLAT | | YEAR | YR | | |
| ENGINE : MODEL S/N | | | | INTERIOR See Photos. 写真参照 | | | | | |
| Oil leakage | <input checked="" type="radio"/> FAIR | Attn | | | INTERIOR COND. | CLEAN | · <input checked="" type="radio"/> FAIR | · DIRTY | |
| Blow-By | <input checked="" type="radio"/> FAIR | Attn | A LITTLE · MIDDLE · SEVERE | | Operator's Seat | <input checked="" type="radio"/> FAIR | Attn | 穴あり HOLES | |
| Sound | <input checked="" type="radio"/> FAIR | Attn | | | Glasses | <input checked="" type="radio"/> FAIR | Attn | | |
| Oil | <input checked="" type="radio"/> FAIR | Attn | | | AirCon | <input checked="" type="radio"/> A/C | · H/C · H only · C only · None | | |
| Exhaust Color | <input checked="" type="radio"/> FAIR | Attn | | | UNDERCARRIAGE : See Photos. 写真参照 | | | | |
| OPERATION PUMP | | | | RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 | | | | | |
| Sound | <input checked="" type="radio"/> FAIR | Attn | | | COMMENT | | | | |
| Oil leakage | <input checked="" type="radio"/> FAIR | Attn | | | | | | | |
| Power | <input checked="" type="radio"/> FAIR | Attn | | | | | | | |
| COOLING SYSTEM | | | | WEIGHT | 3 | | | | |
| Radiator | <input checked="" type="radio"/> FAIR | Attn | | | HOOK | 55t, 30t, LIGHT HOOK | | | |
| Oil Cooler | <input checked="" type="radio"/> FAIR | Attn | | | FREE FALL | <input checked="" type="radio"/> YES | · NO | | |
| OPERATING SYSTEM | | | | LIFTER | YES | · <input checked="" type="radio"/> NO | | | |
| Computer | <input checked="" type="radio"/> OK | · NG | | | COMMENT | | | | |
| Swing | <input checked="" type="radio"/> FAIR | Attn | | | 穴あり HOLES | | | | |
| Travel | <input checked="" type="radio"/> FAIR | Attn | | | ガントリーシリンダーにじみあり GANTRY CYLINDER: OIL Oozing | | | | |
| BOOM | | | | 第3ドラム付 W/3rd DRUM | | | | | |
| MAIN BOOM | TOP, BOTTOM, 9m × 2, 6m × 1, 3m × 2 | | | | | | | | |
| BOOM TOTAL | 40m | | | @NARITA YARD | | | | | |
| TOP SHEAVE | <input checked="" type="radio"/> YES | · NO | | | BOOM: TOP, BOTTOM, 9m × 1 | | | | |
| JIB | | | | HOOK: 30t, LIGHT HOOK | | | | | |
| | | | | @SAKURA YARD | | | | | |
| TOWER | | | | BOOM: 9m × 1, 6m × 1, 3m × 2 | | | | | |
| | | | | 55t HOOK | | | | | |
| | | | | RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1 | | | | | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。