

## INSPECTION SHEET 検品書

## OTHER その他

|                 |  |          |                        |       |           |
|-----------------|--|----------|------------------------|-------|-----------|
| INSPECTION DATE | 2026/1/16                              | CATEGORY | TRAVEL MOTOR for 320EL |       |           |
| MAKE            | CAT                                    |          |                        | MODEL | UNKNOWN   |
| SERIAL          | 15A1932                                |          |                        | STAMP | NOT FOUND |
| HR METER        | HR                                     | Odometer |                        | km    | YEAR      |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE | SHOE     |                        | TIRE  |           |

| ENGINE      | MODEL       | S/N                        |               |             |
|-------------|-------------|----------------------------|---------------|-------------|
| Oil leakage | FAIR • Attn |                            | Oil           | FAIR • Attn |
| Blow-By     | FAIR • Attn | A LITTLE • MIDDLE • SEVERE | Exhaust Color | FAIR • Attn |
| Sound       | FAIR • Attn |                            | EPA           | YES • NO    |

|           |             |  |  |  |
|-----------|-------------|--|--|--|
| CONDITION | FAIR • Attn |  |  |  |
|           |             |  |  |  |
|           |             |  |  |  |
|           |             |  |  |  |
|           |             |  |  |  |

|  |   |           |                           |  |
|--|---|-----------|---------------------------|--|
| UNDERCARRIAGE : See Photos. 写真参照                                     |   |           |                           |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |   | TIRE WEAR | FAIR • WORN • UNEVEN WEAR |  |
| COMMENT  |   |           |                           |  |
|  |   |           |                           |  |
|  |   |           |                           |  |
|  |   |           |                           |  |
|  |   |           |                           |  |
|  |   |           |                           |  |
|  |   |           |                           |  |
|  |   |           |                           |  |
|  |   |           |                           |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |           |                           |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。