

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/20	MAKE	KOMATSU	MODEL	PC200-10
SERIAL	453802		STAMP	KMTPC243EFC453802	
HR METER	8038	HR	YEAR	2015	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE :		MODEL	6D107E-2	S/N	26641214
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	ガタあり SWING: LOOSE		
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	破れあり TORN		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn	*1		
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn	ガタあり LOOSE		
Arm Cylinder	FAIR	Attn			
ATTACHMENT	FAIR	Attn			
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE :						See Photos.						写真参照							
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		3	
COMMENT																			
底板周り油漏れ小 BOTTOM: OIL OOZING																			
BKT				(STD / SLOPE / NARROW / SKELETON / OTHER())															
Lever				LONG ▪ (WRIST)															
Multi				(MULTI) ▪ 2 ▪ NO						油漏れ小 OIL OOZING									
ARM-CRANE				YES ▪ (NO)															
BLADE				YES ▪ (NO)															
OFFSET				YES ▪ (NO)															
OFFSET Cylinder				FAIR ▪ Attn															
Piping				(YES) ▪ NO				Breaker only				(▪ Multi)							
COMMENT																			
*1 ガタ、パッチあり、クラック大 LOOSE, PATCHED, MUCH CRACKED																			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。