

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/1/21	MAKE	CAT	MODEL	D5K2LGP	
SERIAL	CAT00D5KJRRE02180			STAMP	CAT00D5KJRRE02180	
HR METER	1080	HR	SHOE	770LGP	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	DIFF. STEERING (YES) · NO
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	(CLEAN) · FAIR · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
BLADE & CYLINDERS		
BLADE	(FAIR) · Attn	
CYLD.(R)	(FAIR) · Attn	
CYLD.(L)	(FAIR) · Attn	
TILT CYLD	(FAIR) · Attn	
ANGLE CYLD	(FAIR) · Attn	

UNDERCARRIAGE		See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT 			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
COMMENT 			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。