

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/1/26	MAKE	CAT	MODEL	D8H
SERIAL	46A33304			STAMP	NOT FOUND
HR METER	E1618	HR	SHOE	550G	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N
Oil leakage	(FAIR) • Attn	
Blow-By	(FAIR) • Attn	A LITTLE • MIDDLE • SEVERE
Sound	(FAIR) • Attn	
Oil	(FAIR) • Attn	
Exhaust Color	(FAIR) • Attn	
US EPA	YES • (NO)	
OPERATION PUMP		
Sound	(FAIR) • Attn	
Oil leakage	(FAIR) • Attn	
Power	(FAIR) • Attn	
COOLING SYSTEM		
Radiator	(FAIR) • Attn	
Oil Cooler	(FAIR) • Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) • DD	DIFF. STEERING YES • (NO)
Transmission	(FAIR) • Attn	
Travel	(FAIR) • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • (FAIR) • DIRTY	
Operator's Seat	(FAIR) • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • (H only) • C only • None	
BLADE & CYLINDERS		
BLADE	(FAIR) • Attn	
CYLD.(R)	FAIR • (Attn) *1	
CYLD.(L)	(FAIR) • Attn	
TILT CYLD	FAIR • (Attn)	傷あり SCRATCHED
ANGLE CYLD	FAIR • Attn	

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Ripper (MULTI) • S/S Shanks 1 PCS	
Ripper CYLD. (FAIR) • Attn	
COMMENT	
HRメーター故障あり HR METER: MALFUNCTION	
*1 油漏れ小、メッキ剥がれあり OIL LEAKING, COATING: PEELED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。