

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/26	MAKE	YANMAR	MODEL	VIO70-3A
SERIAL	35106B		STAMP	NOT FOUND	
HR METER	2564	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N	92835
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	(YES) · NO		
MAIN PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	(FAIR) · Attn		
OPERATING SYSTEM			
Swing	(FAIR) · Attn		
Travel	FAIR · (Attn)	*1	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	(FAIR) · Attn		
Glasses	FAIR · (Attn)	*2	
AirCon	(A/C) · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	(FAIR) · Attn		
Boom Cylinder	(FAIR) · Attn		
Arm	(FAIR) · Attn		
Arm Cylinder	(FAIR) · Attn		
ATTACHMENT	(FAIR) · Attn		
BKT Cylinder	(FAIR) · Attn		

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · (WRIST)	
Multi	(MULTI) · 2 · NO	
ARM-CRANE	YES · (NO)	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	(YES) · NO (Breaker only) · Multi	
COMMENT		
*1 増速ペダル効かない HI/LO SHIFTING PEDAL: MALFUNCTION		
*2 F下アクリル板に交換あり LOWER WINDSHIELD: ACRYLIC BOARD		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。