

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/23	MAKE	KOMATSU	MODEL	PC55MR-3
SERIAL	18623			STAMP	KMTPC212KEE018623
HR METER	6035	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	400G PADS

ENGINE : MODEL 4D88E S/N 32025

Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	

MAIN PUMP

Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	

COOLING SYSTEM

Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	

OPERATING SYSTEM

Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY
Operator's Seat	<u>FAIR</u> · <u>Attn</u> 破れ小 CUT
Glasses	<u>FAIR</u> · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>

BOOM / ARM / BKT

Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	*1
Arm Cylinder	<u>FAIR</u> · Attn	
ATTACHMENT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · <u>Attn</u>	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

シューパッド:カスが付いているだけ RUBBER PADS: ALMOST GONE

BKT STD / SLOPE / NARROW / SKELETON OTHER FORK GRAB)

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

排ガスシールなし NO EXHAUST GAS LEAKING LEVEL SEAL

E/Gカバー、ラジエータカバー変形小

ENGINE HOOD & RADIATOR HOOD: DISTORTED

*1 先端ピンガタ大 BUCKET SIDE OF PIN: MUCH LOOSE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。