

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/6	MAKE	HITACHI	MODEL	LX80-5
SERIAL	41XP005138			STAMP	L805-5138
HR METER	9071	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">ENGINE : MODEL</td> <td>S/N</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>Blow-By</td> <td>FAIR · Attn</td> <td>A LITTLE · MIDDLE · SEVERE *1</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> <td>異音あり NOISES</td> </tr> <tr> <td>Oil</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR · Attn</td> <td>黒煙あり BLACK FUMES</td> </tr> <tr> <td>US EPA</td> <td>YES · NO</td> <td></td> </tr> <tr> <td colspan="3">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> <td>油漏れあり OIL LEAKING</td> </tr> <tr> <td>Power</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>PS · DD</td> <td></td> </tr> <tr> <td>Transmission</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>Travel</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>FOOT BRAKE</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>PARKING BRAKE</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · FAIR · DIRTY</td> <td></td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR · Attn</td> <td>穴あり HOLES</td> </tr> <tr> <td>Glasses</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>AirCon</td> <td>A/C · H/C · H only · C only · None</td> <td></td> </tr> <tr> <td colspan="3">FRONT & CYLINDERS</td> </tr> <tr> <td>Arm</td> <td>FAIR · Attn</td> <td>*2</td> </tr> <tr> <td>Bell crank</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>Bucket</td> <td>FAIR · Attn</td> <td></td> </tr> <tr> <td>Articulate</td> <td>FAIR · Attn</td> <td></td> </tr> </table>	ENGINE : MODEL		S/N	Oil leakage	FAIR · Attn		Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE *1	Sound	FAIR · Attn	異音あり NOISES	Oil	FAIR · Attn		Exhaust Color	FAIR · Attn	黒煙あり BLACK FUMES	US EPA	YES · NO		OPERATION PUMP			Sound	FAIR · Attn		Oil leakage	FAIR · Attn	油漏れあり OIL LEAKING	Power	FAIR · Attn		COOLING SYSTEM			Radiator	FAIR · Attn		Oil Cooler	FAIR · Attn		TRANSMISSION & TRAVEL			T/M TYPE	PS · DD		Transmission	FAIR · Attn		Travel	FAIR · Attn		FOOT BRAKE	FAIR · Attn		PARKING BRAKE	FAIR · Attn		INTERIOR See Photos. 写真参照			INTERIOR COND.	CLEAN · FAIR · DIRTY		Operator's Seat	FAIR · Attn	穴あり HOLES	Glasses	FAIR · Attn		AirCon	A/C · H/C · H only · C only · None		FRONT & CYLINDERS			Arm	FAIR · Attn	*2	Bell crank	FAIR · Attn		Bucket	FAIR · Attn		Articulate	FAIR · Attn		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>2</td> </tr> <tr> <td>TIRE WEAR</td> <td>FAIR · WORN · UNEVEN WEAR</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">タコメーター TACHOMETER: 62124km</td> </tr> <tr> <td colspan="2">STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING</td> </tr> <tr> <td>RIDE CONTROL</td> <td>YES · NO</td> </tr> <tr> <td colspan="2">ATTACHMENTS</td> </tr> <tr> <td>STD BKT</td> <td>YES · OTHER</td> </tr> <tr> <td>BLADE</td> <td>YES · NO Piping for Tilt YES · NO *3</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">リペイントあり REPAINTED</td> </tr> <tr> <td colspan="2">ワンタッチ付 W/ONE-TOUCH</td> </tr> <tr> <td colspan="2">バケットクイックロックホース左油漏れあり(吸着マットあり)</td> </tr> <tr> <td colspan="2">LEFT HOSE FOR ONE-TOUCH: OIL LEAKING (W/ABSORPTION MAT)</td> </tr> <tr> <td colspan="2">右E/Gルーム内ホース油漏れあり(吸着マットあり)</td> </tr> <tr> <td colspan="2">SOME RIGHT SIDE HOSE IN ENGINE ROOM: OIL LEAKING (W/ABSORPTION MAT)</td> </tr> <tr> <td colspan="2">！マーク表示あり WARNING LAMP: ON</td> </tr> <tr> <td colspan="2">ラジオ不良 RADIO: MALFUNCTION</td> </tr> <tr> <td colspan="2">*1 吸気側よりブローバイあり BLOW-BY FROM THE INTAKE SIDE</td> </tr> <tr> <td colspan="2">*2 左シリンダー油漏れあり(吸着マットあり)</td> </tr> <tr> <td colspan="2">*2 LEFT CYLINDER: OIL LEAKING (W/ABSORPTION MAT)</td> </tr> <tr> <td colspan="2">*3 ホース先4本油漏れあり(吸着マットあり)</td> </tr> <tr> <td colspan="2">*3 TIPS OF 4 PIPES: OIL LEAKING (W/ABSORPTION MATS)</td> </tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">1</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR · WORN · UNEVEN WEAR	COMMENT		タコメーター TACHOMETER: 62124km		STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING		RIDE CONTROL	YES · NO	ATTACHMENTS		STD BKT	YES · OTHER	BLADE	YES · NO Piping for Tilt YES · NO *3	COMMENT		リペイントあり REPAINTED		ワンタッチ付 W/ONE-TOUCH		バケットクイックロックホース左油漏れあり(吸着マットあり)		LEFT HOSE FOR ONE-TOUCH: OIL LEAKING (W/ABSORPTION MAT)		右E/Gルーム内ホース油漏れあり(吸着マットあり)		SOME RIGHT SIDE HOSE IN ENGINE ROOM: OIL LEAKING (W/ABSORPTION MAT)		！マーク表示あり WARNING LAMP: ON		ラジオ不良 RADIO: MALFUNCTION		*1 吸気側よりブローバイあり BLOW-BY FROM THE INTAKE SIDE		*2 左シリンダー油漏れあり(吸着マットあり)		*2 LEFT CYLINDER: OIL LEAKING (W/ABSORPTION MAT)		*3 ホース先4本油漏れあり(吸着マットあり)		*3 TIPS OF 4 PIPES: OIL LEAKING (W/ABSORPTION MATS)		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1	
ENGINE : MODEL		S/N																																																																																																																																													
Oil leakage	FAIR · Attn																																																																																																																																														
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE *1																																																																																																																																													
Sound	FAIR · Attn	異音あり NOISES																																																																																																																																													
Oil	FAIR · Attn																																																																																																																																														
Exhaust Color	FAIR · Attn	黒煙あり BLACK FUMES																																																																																																																																													
US EPA	YES · NO																																																																																																																																														
OPERATION PUMP																																																																																																																																															
Sound	FAIR · Attn																																																																																																																																														
Oil leakage	FAIR · Attn	油漏れあり OIL LEAKING																																																																																																																																													
Power	FAIR · Attn																																																																																																																																														
COOLING SYSTEM																																																																																																																																															
Radiator	FAIR · Attn																																																																																																																																														
Oil Cooler	FAIR · Attn																																																																																																																																														
TRANSMISSION & TRAVEL																																																																																																																																															
T/M TYPE	PS · DD																																																																																																																																														
Transmission	FAIR · Attn																																																																																																																																														
Travel	FAIR · Attn																																																																																																																																														
FOOT BRAKE	FAIR · Attn																																																																																																																																														
PARKING BRAKE	FAIR · Attn																																																																																																																																														
INTERIOR See Photos. 写真参照																																																																																																																																															
INTERIOR COND.	CLEAN · FAIR · DIRTY																																																																																																																																														
Operator's Seat	FAIR · Attn	穴あり HOLES																																																																																																																																													
Glasses	FAIR · Attn																																																																																																																																														
AirCon	A/C · H/C · H only · C only · None																																																																																																																																														
FRONT & CYLINDERS																																																																																																																																															
Arm	FAIR · Attn	*2																																																																																																																																													
Bell crank	FAIR · Attn																																																																																																																																														
Bucket	FAIR · Attn																																																																																																																																														
Articulate	FAIR · Attn																																																																																																																																														
UNDERCARRIAGE : See Photos. 写真参照																																																																																																																																															
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																																																																														
TIRE WEAR	FAIR · WORN · UNEVEN WEAR																																																																																																																																														
COMMENT																																																																																																																																															
タコメーター TACHOMETER: 62124km																																																																																																																																															
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING																																																																																																																																															
RIDE CONTROL	YES · NO																																																																																																																																														
ATTACHMENTS																																																																																																																																															
STD BKT	YES · OTHER																																																																																																																																														
BLADE	YES · NO Piping for Tilt YES · NO *3																																																																																																																																														
COMMENT																																																																																																																																															
リペイントあり REPAINTED																																																																																																																																															
ワンタッチ付 W/ONE-TOUCH																																																																																																																																															
バケットクイックロックホース左油漏れあり(吸着マットあり)																																																																																																																																															
LEFT HOSE FOR ONE-TOUCH: OIL LEAKING (W/ABSORPTION MAT)																																																																																																																																															
右E/Gルーム内ホース油漏れあり(吸着マットあり)																																																																																																																																															
SOME RIGHT SIDE HOSE IN ENGINE ROOM: OIL LEAKING (W/ABSORPTION MAT)																																																																																																																																															
！マーク表示あり WARNING LAMP: ON																																																																																																																																															
ラジオ不良 RADIO: MALFUNCTION																																																																																																																																															
*1 吸気側よりブローバイあり BLOW-BY FROM THE INTAKE SIDE																																																																																																																																															
*2 左シリンダー油漏れあり(吸着マットあり)																																																																																																																																															
*2 LEFT CYLINDER: OIL LEAKING (W/ABSORPTION MAT)																																																																																																																																															
*3 ホース先4本油漏れあり(吸着マットあり)																																																																																																																																															
*3 TIPS OF 4 PIPES: OIL LEAKING (W/ABSORPTION MATS)																																																																																																																																															
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																																															
1																																																																																																																																															

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。