

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/2/17	MAKE	CAT	MODEL	916
SERIAL	5KC01192		STAMP	5KC01192	
HR METER	3229	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		TIRE SIZE	14.00-24	

ENGINE : MODEL 3204 S/N 45V70632	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	YES · <u>NO</u>
OPERATION PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<u>PS</u> · DD
Transmission	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
FOOT BRAKE	<u>FAIR</u> · Attn
PARKING BRAKE	<u>FAIR</u> · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>
Operator's Seat	<u>FAIR</u> · <u>Attn</u> 破れあり HUGE CUT
Glasses	<u>FAIR</u> · <u>Attn</u> シート破れあり COVER SHEET: TORN
AirCon	A/C · H/C · <u>H only</u> · C only · None
FRONT & CYLINDERS	
Arm	<u>FAIR</u> · Attn
Bell crank	<u>FAIR</u> · Attn
Bucket	<u>FAIR</u> · <u>Attn</u> シリンダー油漏れあり CYLINDER: OIL LEAKING
Articulate	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	<u>FAIR</u> · WORN · UNEVEN WEAR
COMMENT	
ステアリングシリンダー左右油漏れあり	
STEERING CYLINDERS: OIL LEAKING	
STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · <u>NO</u>
ATTACHMENTS	
STD BKT	<u>YES</u> · OTHER
BLADE	YES · <u>NO</u> Piping for Tilt <u>YES</u> · NO
COMMENT	
作動油タンク付近油漏れあり	
AROUND HYDRAULIC OIL TANK: OIL LEAKING	
作動油が少ない HYDRAULIC OIL LEVEL: NOT ENOUGH	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。