

INSPECTION SHEET 検品書

OTHER その他

INSPECTION DATE	2026/1/22	CATEGORY	自走式土質改良機 MOBILE SOIL IMPROVEMENT MACHINE			
MAKE	HITACHI		MODEL	SR-G2000		
SERIAL	65XP000101		STAMP	NOT FOUND		
HR METER	6268	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	TIRE	

ENGINE	MODEL	6BG1	S/N	
Oil leakage	FAIR • Attn		Oil	FAIR • Attn
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	Exhaust Color	FAIR • Attn
Sound	FAIR • Attn		EPA	YES • NO

CONDITION	FAIR • Attn	
クレーン動作しない CRANE: NOT WORKING		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT			
クレーン付(3段ブーム、2.6tフック) W/CRANE MAKE: TADANO TM-ZR263J-EL9220 (3-SECTION BOOM, HOOK: 2.6t)			
左右シュールリンク固着あり TRACK LINKS: STUCK			
オイルクーラーにじみあり OIL COOLER: OIL OOZING			
コンベア(フィーダー)ひび割れあり CONVEYOR OF FEEDER: CRACKED			
右サイドカバー閉まらない RIGHT SIDE COVER: UNABLE TO SHUT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。