

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/1/27	MAKE	KOMATSU	MODEL	WA200-6
SERIAL	72451		STAMP	WA105-72451	
HR METER	1290	HR	Odometer	4168	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	17.5-25	
YEAR	2013		YR		

<table style="width: 100%;"> <tr> <td colspan="2">ENGINE : MODEL</td> <td>S/N</td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Blow-By</td> <td>☒ FAIR · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES · ☒ NO</td> <td></td> </tr> <tr> <td colspan="3">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Power</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>☒ PS · DD</td> <td></td> </tr> <tr> <td>Transmission</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Travel</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>FOOT BRAKE</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>PARKING BRAKE</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · ☒ FAIR · DIRTY</td> <td></td> </tr> <tr> <td>Operator's Seat</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Glasses</td> <td>☒ FAIR · Attn</td> <td>F割れあり WINDSHIELD: CRACKED</td> </tr> <tr> <td>AirCon</td> <td>☒ A/C · H/C · H only · C only · None</td> <td></td> </tr> <tr> <td colspan="3">FRONT & CYLINDERS</td> </tr> <tr> <td>Arm</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Bell crank</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Bucket</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Articulate</td> <td>☒ FAIR · Attn</td> <td>ガタあり LOOSE</td> </tr> </table>	ENGINE : MODEL		S/N	Oil leakage	☒ FAIR · Attn		Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Sound	☒ FAIR · Attn		Oil	☒ FAIR · Attn		Exhaust Color	☒ FAIR · Attn		US EPA	YES · ☒ NO		OPERATION PUMP			Sound	☒ FAIR · Attn		Oil leakage	☒ FAIR · Attn		Power	☒ FAIR · Attn		COOLING SYSTEM			Radiator	☒ FAIR · Attn		Oil Cooler	☒ FAIR · Attn		TRANSMISSION & TRAVEL			T/M TYPE	☒ PS · DD		Transmission	☒ FAIR · Attn		Travel	☒ FAIR · Attn		FOOT BRAKE	☒ FAIR · Attn		PARKING BRAKE	☒ FAIR · Attn		INTERIOR See Photos. 写真参照			INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY		Operator's Seat	☒ FAIR · Attn		Glasses	☒ FAIR · Attn	F割れあり WINDSHIELD: CRACKED	AirCon	☒ A/C · H/C · H only · C only · None		FRONT & CYLINDERS			Arm	☒ FAIR · Attn		Bell crank	☒ FAIR · Attn		Bucket	☒ FAIR · Attn		Articulate	☒ FAIR · Attn	ガタあり LOOSE	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>3</td> </tr> <tr> <td>TIRE WEAR</td> <td>FAIR · ☒ WORN · UNEVEN WEAR</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING</td> </tr> <tr> <td>RIDE CONTROL</td> <td>YES · ☒ NO</td> </tr> <tr> <td colspan="2">ATTACHMENTS</td> </tr> <tr> <td>STD BKT</td> <td>☒ YES · OTHER</td> </tr> <tr> <td>BLADE</td> <td>YES · ☒ NO Piping for Tilt YES · ☒ NO</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">リペイントあり REPAINTED</td> </tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">2</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · ☒ WORN · UNEVEN WEAR	COMMENT		STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING		RIDE CONTROL	YES · ☒ NO	ATTACHMENTS		STD BKT	☒ YES · OTHER	BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO	COMMENT		リペイントあり REPAINTED		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2	
ENGINE : MODEL		S/N																																																																																																																			
Oil leakage	☒ FAIR · Attn																																																																																																																				
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																																			
Sound	☒ FAIR · Attn																																																																																																																				
Oil	☒ FAIR · Attn																																																																																																																				
Exhaust Color	☒ FAIR · Attn																																																																																																																				
US EPA	YES · ☒ NO																																																																																																																				
OPERATION PUMP																																																																																																																					
Sound	☒ FAIR · Attn																																																																																																																				
Oil leakage	☒ FAIR · Attn																																																																																																																				
Power	☒ FAIR · Attn																																																																																																																				
COOLING SYSTEM																																																																																																																					
Radiator	☒ FAIR · Attn																																																																																																																				
Oil Cooler	☒ FAIR · Attn																																																																																																																				
TRANSMISSION & TRAVEL																																																																																																																					
T/M TYPE	☒ PS · DD																																																																																																																				
Transmission	☒ FAIR · Attn																																																																																																																				
Travel	☒ FAIR · Attn																																																																																																																				
FOOT BRAKE	☒ FAIR · Attn																																																																																																																				
PARKING BRAKE	☒ FAIR · Attn																																																																																																																				
INTERIOR See Photos. 写真参照																																																																																																																					
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY																																																																																																																				
Operator's Seat	☒ FAIR · Attn																																																																																																																				
Glasses	☒ FAIR · Attn	F割れあり WINDSHIELD: CRACKED																																																																																																																			
AirCon	☒ A/C · H/C · H only · C only · None																																																																																																																				
FRONT & CYLINDERS																																																																																																																					
Arm	☒ FAIR · Attn																																																																																																																				
Bell crank	☒ FAIR · Attn																																																																																																																				
Bucket	☒ FAIR · Attn																																																																																																																				
Articulate	☒ FAIR · Attn	ガタあり LOOSE																																																																																																																			
UNDERCARRIAGE : See Photos. 写真参照																																																																																																																					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																																				
TIRE WEAR	FAIR · ☒ WORN · UNEVEN WEAR																																																																																																																				
COMMENT																																																																																																																					
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING																																																																																																																					
RIDE CONTROL	YES · ☒ NO																																																																																																																				
ATTACHMENTS																																																																																																																					
STD BKT	☒ YES · OTHER																																																																																																																				
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO																																																																																																																				
COMMENT																																																																																																																					
リペイントあり REPAINTED																																																																																																																					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																					
2																																																																																																																					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。