

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/4/3	MAKE	CAT	MODEL	320
SERIAL	3XM02746		STAMP	3XM02746	
HR METER	10799	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE <b>MIDDLE</b> SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · <b>NO</b>	
<b>MAIN PUMP</b>		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油漏れあり OIL LEAKING
Power	FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · <b>FAIR</b> · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUT
Glasses	FAIR · Attn	
AirCon	<b>A/C</b> · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	右油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
右キャリアローラー偏摩耗あり SOME RIGHT CARRIER ROLLER: UNEVEN WEARING	
BKT <b>STD</b> / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG · <b>WRIST</b>
Multi	MULTI · 2 · <b>NO</b>
ARM-CRANE	YES · <b>NO</b>
BLADE	YES · <b>NO</b>
OFFSET	YES · <b>NO</b>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <b>NO</b> Breaker only · Multi
<b>COMMENT</b>	
底板油汚れあり BOTTOM: OIL STAINS プライミングポンプ燃料漏れあり PRIMING PUMP: FUEL LEAKING コントロールバルブにじみあり CONTROL VALVE: OIL OOZING ローアイドルでリリース掛けるとエンストする ENGINE STALLING WITH ENGINE LOAD INCREASING IN LOW IDLING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。