

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANEトラッククレーン / オールテレーンクレーン

INSPECTION DATE	2026/1/6	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE				
MAKE	P&H	MODEL	9170-TC				
SERIAL	NO PLATE	STAMP	NOT FOUND				
HR METER	9815	HR	Odometer	-	km	YEAR	YR
CHASSIS	MODEL	KS150	No.	0066	TIRE	14.00-24	

ENGINE(CRANE) : MODEL		8DC61C	S/N
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE *1
Sound	FAIR	Attn	*1
Oil	FAIR	Attn	*1
Exhaust Color	FAIR	Attn	*1
ENGINE(CHASSIS) : MODEL		10DC61A	S/N 003978
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
OPERATION PUMP			
Sound	FAIR	Attn	*1
Oil leakage	FAIR	Attn	*1
Power	FAIR	Attn	*1
COOLING SYSTEM			
Radiator	FAIR	Attn	目詰まりあり CLOGGED
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Computer	OK	NG	*1
Swing	FAIR	Attn	*1
Travel	FAIR	Attn	*2
TRANSMISSION & TRAVEL			
T/M TYPE	AT	MT	No. OF GEARS 5 GEARS
Transmission	FAIR	Attn	
No. of DRIVE WHEELS	2	WD	
Travel	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり DAMAGED
Glasses	FAIR	Attn	Fガラス亀裂あり WINDSHIELD: CRACKED
AirCon	A/C	H/C	H only · C only · NONE

CRANE	
WEIGHT	4
HOOK	65t, 40t, 10t, BALL
BOOM	
MAIN BOOM	7.3m × 1, 3.05m × 1, 11.14m × 1
BOOM TOTAL	21.49m
No. of Section	SECTIONS
TOP SHEAVE	YES · NO
JIB	STD · PWR 9.85m
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
クレーン側E/G掛からないためクレーン未確認 CRANE OPERATION: NOT CHECKED (CRANE ENGINE: UNABLE TO RUN) シフトレバーチェンジノブからエアー漏れあり SHIFT KNOB: AIR LEAKING シャーンE/Gを長く作動すると温度計が上がり気味 WATER TEMPERATURE GAUGE OF CHASSIS: RISING OVER 100 DEGREES WHEN CHASSIS ENGINE RUNNING FOR LONG TIME スピードメーター欠 SPEEDOMETER: MISSING クレーンの部品多数欠品 MANY PARTS OF CRANE: MISSING *1 未確認 NOT CHECKED *2 パワーステアリング不良 POWER STEERING: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。