# INSPECTION SHEET 検品書
## WHEEL LOADER タイヤショベル

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2026/2/26 | MAKE | CAT | MODEL | 962H |
| SERIAL | CAT0962HPJ6J00592 | | STAMP | CAT0962HPJ6J00592 | |
| HR METER | 28686 HR | Odometer | 150877 km | YEAR | YR |
| CAB/CNP | ROPS CAB (/ CAB /) ROPS CNP / CNP / NONE | | TIRE SIZE | 23.5R25 | |

| ENGINE : MODEL | S/N KHX47842 | |
|---|---|---|
| Oil leakage | FAIR ・(Attn) | *1 |
| Blow-By | (FAIR)・ Attn | A LITTLE・ MIDDLE・ SEVERE |
| Sound | (FAIR)・ Attn | |
| Oil | (FAIR)・ Attn | |
| Exhaust Color | (FAIR)・ Attn | 黒煙あり BLACK FUMES |
| US EPA | YES ・(NO) | |
| **OPERATION PUMP** | | |
| Sound | (FAIR)・ Attn | |
| Oil leakage | (FAIR)・ Attn | |
| Power | (FAIR)・ Attn | |
| **COOLING SYSTEM** | | |
| Radiator | (FAIR)・ Attn | |
| Oil Cooler | (FAIR)・ Attn | |
| **TRANSMISSION & TRAVEL** | | |
| T/M TYPE | (PS)・ DD | |
| Transmission | (FAIR)・ Attn | |
| Travel | (FAIR)・ Attn | |
| FOOT BRAKE | (FAIR)・ Attn | |
| PARKING BRAKE | (FAIR)・ Attn | |
| **INTERIOR** | **See Photos. 写真参照** | |
| INTERIOR COND. | CLEAN ・ (FAIR) ・ DIRTY | |
| Operator's Seat | (FAIR)・ Attn | |
| Glasses | FAIR ・(Attn) | F割れあり WINDSHIELD: CRACKED |
| AirCon | (A/C) ・ H/C ・ H only ・ C only ・ None | |
| **FRONT & CYLINDERS** | | |
| Arm | (FAIR)・ Attn | |
| Bell crank | (FAIR)・ Attn | |
| Bucket | (FAIR)・ Attn | |
| Articulate | (FAIR)・ Attn | |

| UNDERCARRIAGE : See Photos. 写真参照 | | | |
|---|---|---|---|
| **RUST**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | | |
| TIRE WEAR | FAIR (・ WORN ・) UNEVEN WEAR | | |
| **COMMENT** | | | |
| STEERING TYPE | (WHEEL STEERING) / COMMAND STEERING / LEVER STEERING | | |
| RIDE CONTROL | YES ・ (NO) | | |
| **ATTACHMENTS** | | | |
| STD BKT | (YES)・ OTHER | | |
| BLADE | YES ・ (NO) | Piping for Tilt | YES ・ (NO) |
| **COMMENT** | | | |
| 前後進切替レバー動き緩い | | | |
| FORWARD/REVERSE SWITCH LEVER: LOOSE | | | |
| *1 ヘッド周りにじみ、油汚れあり | | | |
| *1 AROUND CYLINDER HEAD: OIL OOZING, OIL STAINS | | | |
| **RUST of BODY**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。