INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/2/24	MAKE	TADANO	MODEL	AT-270-2
SERIAL No.	PLATE : 371352		STAMP : 371352		
HR METER	1510 HR	Odometer	4279 km	YEAR	YR
CHASSIS	MODEL FRR90		No. 7113120		
SHOE			TIRE SIZE	215/70R17.5	
MAX HIGHT	27.0 m		MAX WEIGHT	200 kg	

ENGINE : MODEL 4HK1 S/N 607969		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・(NO)	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT・(MT)	No. OF GEARS 6 GEARS
Transmission	FAIR・Attn	
4WD	4WD・(2WD)	
Travel	FAIR・Attn	
Swing	FAIR・Attn	
FOOT BRAKE	FAIR・Attn	
PARKING BRAKE	FAIR・Attn	
BOOM		
No. of Section	4 SECTIONS	
DERRICKING CYL.	FAIR・(Attn)	油漏れあり OIL LEAKING
EXTENSION CYL.	(FAIR)・Attn	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
TIRE WEAR	FAIR・(WORN)・UNEVEN WEAR	
COMMENT		
OUTRIGGERS	X ・ (H)	
OUTRIGGERS COND.	(FAIR) ・ Attn	
COMMENT		
バケット首振りガタあり BUCKET SWING: LOOSE		
リペイントあり REPAINTED		
最高出力 MAXIMUM OUTPUT: 140kW (190PS)/2600rpm		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。