

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/2/19	MAKE	NIPPON SHARYO	MODEL	DH350
SERIAL No.	PLATE : 37101	STAMP		NOT FOUND	
HR METER	3632	HR	SHOE	770FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 5	
BOOM TOTAL	40m	
TOP SHEAVE	YES · <input checked="" type="radio"/> NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY	
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり DAMAGED
Glasses	FAIR · Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
WEIGHT 3		
HOOK 35t, BALL		
FREE FALL	<input checked="" type="radio"/> YES · NO	
LIFTER	YES · <input checked="" type="radio"/> NO	
COMMENT		
ヒーター&クーラー風が出ない HEATER & COOLER: NOT BLOWING AIR		
E/Gストップ不良 ENGINE STOPPER: MALFUNCTION		
*1 E/Gとオイルパンの繋ぎ目油漏れあり		
*1 CONNECTING PART BETWEEN ENGINE BLOCK & OIL PAN: OIL LEAKING		
リペイントあり REPAINTED		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。