

INSPECTION SHEET 検品書
TRUCKトラック

INSPECTION DATE	2026/2/19	MAKE	MITSUBISHI	MODEL	KC-FV519JXD
SERIAL	701022			STAMP	FV519JX-701022
HR METER	290	HR	Odometer	176780	km
TIRE	11R22.5			YEAR	YR

ENGINE : MODEL 8DC11 S/N			
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	AT	☒ MT	No. OF GEARS 6 GEARS
Transmission	☒ FAIR	Attn	
4WD	4WD	☒ 2WD	
Travel	☒ FAIR	Attn	
FOOT BRAKE	☒ FAIR	Attn	
PARKING BRAKE	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	☒ FAIR	DIRTY
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C	H/C · H only · C only · NONE	
OUTRIGGERS / JACK			
OUTRIGGERS	X	H	
CONDITION	☒ FAIR	Attn	
JACK	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR			
COMMENT			
BODY			
CATEGORY	バークブローワー BARK BLOWER		
MAKE	FINN		
MODEL	BB-1216	SERIAL	SDS-379
CONDITION	☒ FAIR	Attn	
MAIN FRAME	☒ FAIR	Attn	
CRANE			
MAKE			
MODEL		SERIAL	
No. of Section	SECTIONS		
HOOK			
RADIO CONTROL	YES	☒ NO	
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			
			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。