

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	2026/4/6	MAKE	TADANO	MODEL	TR-160M-3
SERIAL No.	PLATE : 525473	STAMP :		TR162-0097	
HR METER	9517	HR	Odometer	85639	km
TIRE SIZE	325/95R24		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn	上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input checked="" type="radio"/> SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	黒煙あり BLACK FUMES
<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	*1
Travel	FAIR <input checked="" type="radio"/> Attn	公道走行不可 UNABLE TO RUN ON PUBLIC ROADS
<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4 GEARS	
4WD	4WD <input checked="" type="radio"/> 6WD	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN <input checked="" type="radio"/> FAIR <input checked="" type="radio"/> DIRTY	
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	破れあり HOLE, CUTS
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	
<b>COMMENT</b>		
ウインチモーターソレノイドブロック油漏れあり		
WINCH SOLENOID BLOCK: OIL LEAKING		
メインS/Wあり W/MAIN SWITCH		

<b>BOOM</b>			
No. of Section	6 SECTIONS		
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn		
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn		
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn		
JIB	YES <input type="radio"/> NO <input checked="" type="radio"/>		
JIB TYPE	STD <input type="radio"/> PWR		
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO	乱巻きあり IRREGULAR WINDING	
FREE FALL	YES <input checked="" type="radio"/> NO		
HOOK	-		
<b>UNDERCARRIAGE : See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN <input checked="" type="radio"/>	UNEVEN WEAR	
<b>COMMENT</b>			
左Rタイヤ摩耗大、側面ひび割れあり			
REAR LEFT TIRE: MUCH WORN, SIDEWALL: CRACKED			
<b>OUTRIGGERS</b>			
OUTRIGGERS	X <input checked="" type="radio"/> H	下で操作 NEED TO OPERATE FROM OUTSIDE	
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L <input type="radio"/> R <input type="radio"/>	REAR L <input type="radio"/> R <input type="radio"/>
Oil leakage (SLIDE CYL.)	FRONT	L <input type="radio"/> R <input type="radio"/>	REAR L <input type="radio"/> R <input type="radio"/>
<b>COMMENT</b>			
基礎仕様(アボロン) FOUNDATION WORK MACHINE (AVALON)			
ブーム操作未確認 BOOM OPERATIONS: NOT CHECKED			
*1 操作未確認、スイベル油漏れあり			
*1 OPERATION: NOT CHECKED, SWIVEL: OIL LEAKING			
@SAKURA YARD			
HOOK: 16t, BALL, SINGLE TOP, HOOK HOLDER, WEDGE SOCKET, AUGER (1 AXIS)			
AVALON LEADER: 4.5m × 2, 3m × 1, 2m × 1, 1.5m END			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。