

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2026/4/3	MAKE	MITSUBISHI	MODEL	BD2H
SERIAL	-	STAMP	2B351045		
HR METER	ERROR	HR	SHOE	1000LGP	YEAR
BLADE	STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS <u>CNP</u> / CNP / NONE	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
<b>OPERATION PUMP</b>		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	PS · <u>DD</u>	DIFF. STEERING
		YES · <u>NO</u>
Transmission	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
<b>BLADE &amp; CYLINDERS</b>		
BLADE	<u>FAIR</u> · Attn	
CYLD.(R)	<u>FAIR</u> · Attn	
CYLD.(L)	<u>FAIR</u> · Attn	ロッドサビあり ROD: RUSTY
TILT CYLD	<u>FAIR</u> · Attn	
ANGLE CYLD	FAIR · Attn	

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
<b>COMMENT</b>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<u>FAIR</u> · Attn		
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。