

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

|                 |           |        |          |            |           |
|-----------------|-----------|--------|----------|------------|-----------|
| INSPECTION DATE | 2026/3/10 | MAKE   | TADANO   | MODEL      | TR-250M-5 |
| SERIAL No.      | PLATE :   | 519817 | STAMP :  | TR253-1424 |           |
| HR METER        | 1005      | HR     | Odometer | 44844      | km        |
| TIRE SIZE       | 17.5R29   | YEAR   | YR       |            |           |

| ENGINE : MODEL                   | S/N   |
|----------------------------------|---|
| Oil leakage                      | <input type="radio"/> FAIR · Attn                                   |
| Blow-By                          | <input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE        |
| Sound                            | <input type="radio"/> FAIR · Attn                                   |
| Oil                              | <input type="radio"/> FAIR · Attn                                   |
| Exhaust Color                    | <input type="radio"/> FAIR · Attn                                   |
| <b>OPERATION PUMP</b>            |   |
| Sound                            | <input type="radio"/> FAIR · Attn                                   |
| Oil leakage                      | <input type="radio"/> FAIR · Attn                                   |
| Power                            | <input type="radio"/> FAIR · Attn                                   |
| <b>COOLING SYSTEM</b>            |   |
| Radiator                         | <input type="radio"/> FAIR · Attn                                   |
| Oil Cooler                       | <input type="radio"/> FAIR · Attn                                   |
| <b>OPERATING SYSTEM</b>          |   |
| Computer                         | <input checked="" type="radio"/> OK · NG                            |
| Swing                            | <input type="radio"/> FAIR · Attn                                   |
| Travel                           | <input type="radio"/> FAIR · Attn                                   |
| <b>TRANSMISSION</b>              |   |
| Transmission                     | <input type="radio"/> FAIR · Attn                                   |
| No. OF GEARS                     | 3 GEARS   |
| 4WD                              | <input type="radio"/> 4WD · 6WD                                     |
| <b>INTERIOR See Photos. 写真参照</b> |   |
| INTERIOR COND.                   | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY               |
| Operator's Seat                  | <input type="radio"/> FAIR · Attn                                   |
| Glasses                          | <input type="radio"/> FAIR · Attn                                   |
| AirCon                           | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |
| <b>COMMENT</b>                   |   |
|                                  |   |

| BOOM   |  |
|--|--|
| No. of Section   | 4 SECTIONS   |
| CRACK/ENFORCEMENT  | <input type="radio"/> FAIR · Attn                          |
| DERRICKING CYL.  | <input type="radio"/> FAIR · Attn                          |
| EXTENSION CYL.   | <input type="radio"/> FAIR · Attn                          |
| JIB  | <input checked="" type="radio"/> YES · NO                  |
| JIB TYPE   | <input type="radio"/> STD · PWR                            |
| MAIN & SUB WIRE  | <input checked="" type="radio"/> YES · NO                  |
| FREE FALL  | <input type="radio"/> YES · NO                             |
| HOOK   | 25t, BALL  |
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)         | 3  |
| TIRE WEAR  | <input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR |
| <b>COMMENT</b>   |  |
|  |  |
| <b>OUTRIGGERS</b>  |  |
| OUTRIGGERS   | <input checked="" type="radio"/> X · H                     |
| OUTRIGGERS COND.   | <input type="radio"/> FAIR · Attn                          |
| Oil leakage (JACK CYL.)  | FRONT L · R REAR L · R                                     |
| Oil leakage (SLIDE CYL.)   | FRONT L · R REAR L · R                                     |
| <b>COMMENT</b>   |  |
|  |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。