INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/3/16	MAKE	TOYOTA	MODEL	60-5FD25
SERIAL	605FD25-11356	STAMP	605FD25-11356		
HR METER	10794 HR	Odometer	- km	YEAR	YR
CAB/CNP	CAB / (CNP) / NONE	TIRE SIZE	F: 5.50-15 8PR / R: 6.50-10/5.00 SOLID		
MAX LIFTING HEIGHT	3.5 m (VIEW) / MONO	FORK LENGTH	850 mm		
FORK SPEC	フルフリー、ヒンジフォーク FULL FREE, HINGED FORK				

ENGINE : MODEL S/N		
Oil leakage	FAIR (Attn)	*1
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · (DD)	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	FAIR · (Attn)	弱い BRAKE: LOOSE
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	FAIR · (Attn)	破れあり MUCH TINY CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
HYDRAULICS		
MAST Cylinder	(FAIR) · Attn	
TILT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR

COMMENT

E/Gフードダンパー不良 ENGINE HOOD DAMPER: MALFUNCTION

*1 ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。