

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2026/2/24	MAKE	KUBOTA	MODEL	RX-502
SERIAL	NO PLATE		STAMP	RX502-10231	
HR METER	5088	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	400R	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
<b>MAIN PUMP</b>		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>	
Operator's Seat	<u>FAIR</u> · <u>Attn</u>	切れあり HUGE CUT
Glasses	<u>FAIR</u> · <u>Attn</u>	*1
AirCon	A/C · H/C · <u>H only</u> · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
ATTACHMENT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	STD · <u>SLOPE</u> · NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	<u>YES</u> · NO
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
<b>COMMENT</b>	
右上部バッテリーカバーラッチ不良のため閉まらない	
RIGHT TOP COVER: UNABLE TO SHUT (LATCH: MALFUNCTION)	
CABドア欠 DOOR: MISSING	
*1 CAB上、R欠、ルーフ亀裂あり	
*1 UPPER WINDSHIELD & REAR GLASS: MISSING, SKYLIGHT: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。