

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/2/24	MAKE	CAT	MODEL	938M
SERIAL	CAT0938MEJ3R04861			STAMP	CAT0938MEJ3R04861
HR METER	15892	HR	Odometer	50600	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5R25

ENGINE : MODEL C7.1 S/N D8T31172	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn *1
AirCon	A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · Attn
Bell crank	FAIR · Attn
Bucket	FAIR · Attn
Articulate	FAIR · Attn *2

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
Fデフ油漏れあり FRONT DIFFERENTIAL: OIL LEAKING	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
ラジエータファン周りホースヒビあり(全体的にホースヒビあり)	
SOME HOSES AROUND RADIATOR FAN: MUCH CRACKED	
バックカメラ不良 BACK MONITOR: MALFUNCTION	
! マーク表示あり WARNING LAMP: ON	
作業装置障害表示あり	
"351-8" ERROR DISPLAY FOR IMPLEMENT	
*1 F左下、F割れあり	
*1 LOWER LEFT WINDSHIELD & WINDSHIELD: CRACKED	
*2 右シリンダー油漏れ小、中折れ周りホースヒビあり	
*2 RIGHT CYLINDER: OIL LEAKING, SOME HOSES: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。