

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/2/27	MAKE	HITACHI	MODEL	ZX210K-3
SERIAL	HCM1U300A00204981		STAMP	HCM1U300A00204981	
HR METER	8119	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600FLAT	

ENGINE : MODEL 4HK1		S/N 417703	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	<input checked="" type="radio"/> YES · NO		

MAIN PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn にじみあり OIL OOZING
Power	<input checked="" type="radio"/> FAIR · Attn

COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn 配管周り油漏れあり SOME PIPE: OIL LEAKING

OPERATING SYSTEM	
Swing	<input checked="" type="radio"/> FAIR · Attn ガタあり SWING: LOOSE
Travel	<input checked="" type="radio"/> FAIR · Attn *1

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり TORN
Glasses	<input checked="" type="radio"/> FAIR · Attn F上部欠 UPPER WINDSHIELD: BROKEN
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

BOOM / ARM / BKT	
Boom	<input checked="" type="radio"/> FAIR · Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn
Arm	<input checked="" type="radio"/> FAIR · Attn ガタあり LOOSE
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn
ATTACHMENT	<input checked="" type="radio"/> FAIR · Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn 傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

COMMENT	
底板周りにじみあり BOTTOM: OIL OOZING	
左右シューリンク固着あり TRACK LINKS: STUCK	

BKT	STD / SLOPE / NARROW / SKELETON (<input checked="" type="radio"/> OTHER)
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · Multi 5

COMMENT	
アタッチメント: 回転式カッター ATTACHMENT: ROTATABLE CUTTER	
カッター挟み込み動作遅い? CUTTER: SLOW TO CLOSE?	
ブーム背面ホースヒビあり	
SOME HOSES AROUND BOOM: A LITTLE DAMAGED	
クランプアーム付(本体上がらない)	
W/CLAMP ARM (UNABLE TO PUSH UP THE BODY BY CLAMP ARM)	
燃料フィルターにじみあり FUEL FILTER: OIL OOZING	
バッテリーチャージランプ点灯あり BATTERY WARNING LAMP: ON	
*1 速度遅い(パワー弱い?) SLOW TRAVELING (WEAK POWER?)	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。