

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/3	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE :	5115007		STAMP :	KRC005-5007
HR METER	29148	HR	Odometer	95932	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
OPERATION PUMP		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	にじみあり OIL OOZING
Power	FAIR <input checked="" type="radio"/> Attn	
COOLING SYSTEM		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
OPERATING SYSTEM		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
TRANSMISSION		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4 GEARS	
4WD	4WD <input checked="" type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR <input checked="" type="radio"/> DIRTY	
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None	
COMMENT		

BOOM			
No. of Section	4	SECTIONS	
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn		
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn		
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn		
JIB	YES <input checked="" type="radio"/> NO		
JIB TYPE	STD · PWR <input checked="" type="radio"/>		
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO		
FREE FALL	YES · NO <input checked="" type="radio"/>		
HOOK	25t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)			4
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN <input checked="" type="radio"/>	UNEVEN WEAR	
COMMENT			
Rステアリングシリンダーホース先ににじみあり			
TIP OF REAR STEERING CYLINDER HOSE: OIL OOZING			
OUTRIGGERS			
OUTRIGGERS	X · H <input checked="" type="radio"/>		
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
*1 オイルパン下ににじみあり BOTTOM OF OIL PAN: OIL OOZING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。