

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/3/27	MAKE	TADANO	MODEL	TR-160M-2
SERIAL No.	PLATE :	525167	STAMP :	TR161-0051	
HR METER	3390	HR	Odometer	2443	km
TIRE SIZE	325/95R24	YEAR	YR		

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn	油漏れあり OIL LEAKING
Power	<input type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
TRANSMISSION		
Transmission	<input type="radio"/> FAIR · Attn	
No. OF GEARS	3 GEARS	
4WD	<input type="radio"/> 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input type="radio"/> FAIR · <input type="radio"/> Attn	切れ、破れあり HUGE CUTS
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
COMMENT		

BOOM			
No. of Section	4 SECTIONS		
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · Attn		
DERRICKING CYL.	<input type="radio"/> FAIR · Attn		
EXTENSION CYL.	<input type="radio"/> FAIR · Attn		
JIB	YES · <input checked="" type="radio"/> NO		
JIB TYPE	STD · PWR		
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO		
FREE FALL	<input checked="" type="radio"/> YES · NO		
HOOK	16t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)			3
TIRE WEAR		<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR	
COMMENT			
OUTRIGGERS			
OUTRIGGERS	<input checked="" type="radio"/> X · H		
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。