

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2026/3/19	MAKE	KATO	MODEL	HD820-6
SERIAL	KWJ21E01CF0005509		STAMP	5509	
HR METER	3604	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

**ENGINE : MODEL** 4M50 **S/N** D89797

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

**MAIN PUMP**

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

**OPERATING SYSTEM**

Swing	FAIR	Attn	
Travel	FAIR	Attn	

**INTERIOR See Photos. 写真参照**

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

**BOOM / ARM / BKT**

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

**UNDERCARRIAGE : See Photos. 写真参照**

**RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

**COMMENT**

.....

.....

.....

.....

.....

**BKT** (STD / SLOPE / NARROW / SKELETON / OTHER ( ) )

**Lever** LONG · WRIST

**Multi** MULTI · 2 · NO

**ARM-CRANE** YES · NO

**BLADE** YES · NO

**OFFSET** YES · NO

**OFFSET Cylinder** FAIR · Attn

**Piping** YES · NO Breaker only · Multi

**COMMENT**

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

**RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。