

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/3/19	MAKE	KOMATSU	MODEL	D20PLL-7E
SERIAL	62692		STAMP	D20PL7E-62692	
HR METER	6044	HR	SHOE	1050LGP	YEAR 1998 YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Blow-By (FAIR) · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Oil (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color (FAIR) · Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES · (NO)</td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Oil leakage (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Power (FAIR) · Attn</td> <td></td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>PS · (DD) DIFF. STEERING YES · (NO)</td> </tr> <tr> <td>Transmission (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Travel (FAIR) · Attn</td> <td></td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · (FAIR) · DIRTY</td> </tr> <tr> <td>Operator's Seat (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Glasses (FAIR) · Attn</td> <td></td> </tr> <tr> <td>AirCon</td> <td>(A/C) · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE (FAIR) · Attn</td> <td></td> </tr> <tr> <td>CYLD.(R) (FAIR) · Attn</td> <td></td> </tr> <tr> <td>CYLD.(L) (FAIR) · Attn</td> <td></td> </tr> <tr> <td>TILT CYLD (FAIR) · Attn</td> <td></td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR · Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage (FAIR) · Attn		Blow-By (FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	Sound (FAIR) · Attn		Oil (FAIR) · Attn		Exhaust Color (FAIR) · Attn		US EPA	YES · (NO)	OPERATION PUMP		Sound (FAIR) · Attn		Oil leakage (FAIR) · Attn		Power (FAIR) · Attn		COOLING SYSTEM		Radiator (FAIR) · Attn		Oil Cooler	FAIR · Attn	TRANSMISSION & TRAVEL		T/M TYPE	PS · (DD) DIFF. STEERING YES · (NO)	Transmission (FAIR) · Attn		Travel (FAIR) · Attn		INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN · (FAIR) · DIRTY	Operator's Seat (FAIR) · Attn		Glasses (FAIR) · Attn		AirCon	(A/C) · H/C · H only · C only · None	BLADE & CYLINDERS		BLADE (FAIR) · Attn		CYLD.(R) (FAIR) · Attn		CYLD.(L) (FAIR) · Attn		TILT CYLD (FAIR) · Attn		ANGLE CYLD	FAIR · Attn	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">2</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> </td> </tr> <tr> <td>Ripper</td> <td>MULTI · S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> </td> </tr> <tr> <td>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">3</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	COMMENT				Ripper	MULTI · S/S Shanks PCS	Ripper CYLD.	FAIR · Attn	COMMENT				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
ENGINE : MODEL	S/N																																																																												
Oil leakage (FAIR) · Attn																																																																													
Blow-By (FAIR) · Attn	A LITTLE · MIDDLE · SEVERE																																																																												
Sound (FAIR) · Attn																																																																													
Oil (FAIR) · Attn																																																																													
Exhaust Color (FAIR) · Attn																																																																													
US EPA	YES · (NO)																																																																												
OPERATION PUMP																																																																													
Sound (FAIR) · Attn																																																																													
Oil leakage (FAIR) · Attn																																																																													
Power (FAIR) · Attn																																																																													
COOLING SYSTEM																																																																													
Radiator (FAIR) · Attn																																																																													
Oil Cooler	FAIR · Attn																																																																												
TRANSMISSION & TRAVEL																																																																													
T/M TYPE	PS · (DD) DIFF. STEERING YES · (NO)																																																																												
Transmission (FAIR) · Attn																																																																													
Travel (FAIR) · Attn																																																																													
INTERIOR See Photos. 写真参照																																																																													
INTERIOR COND.	CLEAN · (FAIR) · DIRTY																																																																												
Operator's Seat (FAIR) · Attn																																																																													
Glasses (FAIR) · Attn																																																																													
AirCon	(A/C) · H/C · H only · C only · None																																																																												
BLADE & CYLINDERS																																																																													
BLADE (FAIR) · Attn																																																																													
CYLD.(R) (FAIR) · Attn																																																																													
CYLD.(L) (FAIR) · Attn																																																																													
TILT CYLD (FAIR) · Attn																																																																													
ANGLE CYLD	FAIR · Attn																																																																												
UNDERCARRIAGE See Photos. 写真参照																																																																													
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																												
COMMENT																																																																													
Ripper	MULTI · S/S Shanks PCS																																																																												
Ripper CYLD.	FAIR · Attn																																																																												
COMMENT																																																																													
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																												

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。