INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2026/3/27	CATEGORY	ON-ROAD DUMP ・ (OFF-ROAD DUMP)
MAKE	KOMATSU	MODEL	HD405-7
SERIAL	7523	STAMP	KMTHD030A26007523
HR METER	31318 HR	ODOMETER	236013 km
TIRE SIZE	18.00R33	YEAR	YR

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) ・ Attn	
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	
US EPA	YES ・(NO)	

OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	

COOLING SYSTEM		
Radiator	(FAIR) ・ Attn	
Oil Cooler	(FAIR) ・ Attn	

TRANSMISSION & TRAVEL				
T/M TYPE	(AT) ・ MT		No. OF GEARS	6 GEARS
Transmission	(FAIR) ・ Attn			
4WD	4WD ・(2WD)			
Travel	(FAIR) ・ Attn			
Articulate	FAIR ・ Attn			
FOOT BRAKE	(FAIR) ・ Attn			
PARKING BRAKE	(FAIR) ・ Attn			

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR) ・ Attn	
Glasses	(FAIR) ・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	

MAIN FRAME		
MAIN FLAME	(FAIR) ・ Attn	

VESSEL		
MAKE		
VESSEL	(FAIR) ・ Attn	
REAR GATE TYPE	NORMAL ・ L-GATE (FLAT)	
REAR GATE	FAIR ・ Attn	

UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR ・ WORN ・ (UNEVEN WEAR)	

COMMENT

ROPS-CAB

ベッセル内部材あり SOME PARTS: PUTTING IN VESSEL

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。