INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/3/12	MAKE	TOYOTA	MODEL	20-2FD135
SERIAL	202FD135-10055			STAMP	202FD135-10055
HR METER	7822 HR	Odometer	13722 km	YEAR	YR
CAB/CNP	(CAB) / CNP / NONE			TIRE SIZE	11.00-20
MAX LIFTING HEIGHT	3.0 m	(VIEW) / MONO		FORK LENGTH	1950 mm
FORK SPEC					

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	FAIR · (Attn)	*1
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	FAIR · (Attn)	オイル混入あり OIL: MIXED
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	FAIR · (Attn)	効かない MALFUNCTION
INTERIOR	**See Photos. 写真参照**	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	A/C · H/C · (H only) · C only · None	
HYDRAULICS		
MAST Cylinder	FAIR · (Attn)	*2
TILT Cylinder	FAIR · (Attn)	*3

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR	

COMMENT

E/Gストップ効かない ENGINE STOPPER: MALFUNCTION

燃料メーター不良 FUEL GAUGE: MALFUNCTION

左ドアラッチ掛かりにくい LEFT DOOR LATCH: HARD TO CATCH

ヒーター風出ない HEATER: NOT BLOWING AIR

*1 油漏れあり(吸着マットあり) OIL LEAKING (W/ABSORPTION MAT)

*2 左右メッキ剥がれあり CYLINDERS: COATING PEELED

*3 左側メッキ剥がれあり LEFT CYLINDER: COATING PEELED

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。