INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/3/9		MAKE	MOROOKA		MODEL	MF-25V
SERIAL	20187				STAMP	NOT FOUND	
HR METER	3296 HR	Odometer	– km		YEAR	2005 YR	
CAB/CNP	CAB / (CNP) / NONE				TIRE SIZE	–	
MAX LIFTING HEIGHT	3.0 m	(VIEW) / MONO			FORK LENGTH	1100 mm	
FORK SPEC							

ENGINE : MODEL V2203 S/N 05C0008		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	FAIR · (Attn)	黒煙小 A LITTLE BLACK FUMES
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	FAIR · (Attn)	*1
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
HYDRAULICS		
MAST Cylinder	(FAIR) · Attn	
TILT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT

SHOE: 350R

E/G掛かり悪い？(セルモーター接触悪い？)

HARD TO START THE ENGINE

(STARTER MOTOR : LOOSE CONNECTION?)

付属品:ラバーシュー RUBBER SHOE AS SPARE

*1 走行レバー中立になりづらい、増速S/W不良

*1 TRAVEL LEVER: HARD TO KEEP AT THE NEUTRAL POSITION,

HI/LO SWITCH: MALFUNCTION

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。