

OTHER その他

CONDITION	FAIR	Attn	
未確認 OPERATION: NOT CHECKED			

UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR			
COMMENT						
35φ × 165mm						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。