

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/12	MAKE	KOMATSU	MODEL	PC200-10
SERIAL	454077		STAMP	KMTPC243T????????? SOME LETTERS: UNREADABLE	
HR METER	5939	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 6D107E-2 **S/N** 26643147

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C · H only · C only · None	

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	ガタ、ヘコミあり LOOSE, DENT
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	塗料付着あり PAINTY

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2

COMMENT

.....

BKT STD (SLOPE) NARROW / SKELETON / OTHER ()

Lever LONG · (WRIST)

Multi MULTI · 2 · (NO)

ARM-CRANE YES · NO

BLADE YES · (NO)

OFFSET YES · (NO)

OFFSET Cylinder FAIR · Attn

Piping YES · (NO) Breaker only · Multi

COMMENT

左サイドカバーラッチ破損あり LEFT SIDE COVER LATCH: BROKEN
 左サイドカバー一部欠 SOME LEFT SIDE COVER: MISSING
 A/Cフィルターカバー欠 A/C FILTER COVER: MISSING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。