

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/3/10	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB2762		STAMP : TR255-1287		
HR METER	12559	HR	Odometer	39217	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Exhaust Color	<input type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil leakage	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	ポンプ油漏れあり OIL LEAKING
Power	<input type="radio"/> FAIR · <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil Cooler	<input type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · <input type="radio"/> NG	
Swing	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	未確認 OPERATION: NOT CHECKED
Travel	<input type="radio"/> FAIR · <input type="radio"/> Attn	*1
TRANSMISSION		
Transmission	<input type="radio"/> FAIR · <input type="radio"/> Attn	
No. OF GEARS	4 GEARS	
4WD	<input checked="" type="radio"/> 4WD · <input type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	<input type="radio"/> CLEAN · <input type="radio"/> FAIR · <input checked="" type="radio"/> DIRTY	
Operator's Seat	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	破れあり CUTS
Glasses	<input type="radio"/> FAIR · <input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
COMMENT		

BOOM	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 未確認 NOT CHECKED
DERRICKING CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 未確認 NOT CHECKED
EXTENSION CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 未確認 NOT CHECKED
JIB	<input type="radio"/> YES · <input checked="" type="radio"/> NO
JIB TYPE	<input type="radio"/> STD · <input type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · <input type="radio"/> NO サードウインチあり W/3rd WINCH
FREE FALL	<input checked="" type="radio"/> YES · <input type="radio"/> NO
HOOK	25t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	3
TIRE WEAR	<input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR
COMMENT	
右Rサイドウォールクラックあり REAR RIGHT TIRE SIDEWALL: CRACKED	
OUTRIGGERS	
OUTRIGGERS	<input checked="" type="radio"/> X · <input type="radio"/> H
OUTRIGGERS COND.	<input type="radio"/> FAIR · <input type="radio"/> Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
リーダー、オーガー動作未確認	
OPERATIONS OF LEADER & AUGER: NOT CHECKED	
*1 タイヤクラックのため走行不可	
*1 WARNING TO TRAVEL (REAR RIGHT TIRE SIDEWALL: CRACKED)	
@SAKURA YARD	
HOOK: 25t, BALL, SINGLE TOP	
LEADER: 5m × 1, 4.5m × 2, 2m × 1, 1m × 1	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。