INSPECTION SHEET 検品書

CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/3/16	MAKE	IHI	MODEL	IC75
SERIAL	CA003312			STAMP	CA003312
HR METER	3994 HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE			SHOE	700R
TIRE					

ENGINE : MODEL 6HK1 S/N 585342		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	No. OF GEARS 2 GEARS
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
Swing	FAIR · Attn	
Articulate	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	

MAIN FRAME		
MAIN FLAME	(FAIR) · Attn	
VESSEL		
VESSEL	(FAIR) · Attn	
REAR GATE TYPE	NORMAL · L-GATE (FLAT)	
REAR GATE	FAIR · Attn	
UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	

COMMENT

リペイントあり REPAINTED

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。