

INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2026/3/9	CATEGORY	ON-ROAD DUMP <input type="checkbox"/> <input checked="" type="checkbox"/> OFF-ROAD DUMP
MAKE	CAT		MODEL D400D
SERIAL	8TF00193		STAMP NOT FOUND
HR METER	9974	HR	ODOMETER - km
TIRE SIZE	29.5R25		YEAR YR

ENGINE : MODEL 3406B S/N 70V33694			
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES	<input checked="" type="radio"/> NO	
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	<input checked="" type="radio"/> Attn	オイル混入あり OIL: MIXED
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> AT	MT	No. OF GEARS 4 GEARS
Transmission	<input checked="" type="radio"/> FAIR	Attn	
4WD	<input checked="" type="radio"/> 4WD	2WD	
Travel	<input checked="" type="radio"/> FAIR	Attn	
Articulate	FAIR	<input checked="" type="radio"/> Attn	*1
FOOT BRAKE	<input checked="" type="radio"/> FAIR	Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	<input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	破れあり TORN
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	A/C	<input checked="" type="radio"/> H/C	H only · C only · None

MAIN FRAME	
MAIN FLAME	<input checked="" type="radio"/> FAIR · Attn
VESSEL	
MAKE	
VESSEL	FAIR · <input checked="" type="radio"/> Attn *2
REAR GATE TYPE	NORMAL · L-GATE (FLAT)
REAR GATE	FAIR · Attn
UNDERCARRIAGE: See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR
COMMENT	
中折れ周りホース破れ、ヒビあり	
SOME HOSES AROUND ARTICULATE PART: MUCH CRACKED	
ポンプ下ホース油漏れあり	
SOME HOSE UNDER THE PUMP: OIL LEAKING	
ヒーター&クーラーつまみ固着気味 HEATER & COOLER KNOBS: STUCK	
ベッセル内部材あり SOME PART: PUTTING ON VESSEL	
ベッセル内部材ありのためベッセル最大までリフトは未確認	
VESSEL: NOT CHECKED TO LIFT UP FULLY	
(SOME PART: PUTTING ON VESSEL)	
リアデフ油漏れあり REAR DIFFERENTIAL: OIL LEAKING	
*1 左シリンダーメッキ剥がれ、にじみあり	
*1 LEFT CYLINDER: COATING PEELED, OIL OOZING	
*2 ベッセル左側シリンダーにじみ、右側シリンダー油漏れあり	
*2 LEFT CYLINDER: OIL OOZING, RIGHT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。