INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/3/18	MAKE	TCM	MODEL	FHD100Z
SERIAL	91A01141		STAMP	F52-01141	
HR METER	5028 HR	Odometer	63808 km	YEAR	YR
CAB/CNP	(CAB) / CNP / NONE		TIRE SIZE	9.00-20	
MAX LIFTING HEIGHT	4.0 m	(VIEW) / MONO	FORK LENGTH	1950 mm	
FORK SPEC					

ENGINE : MODEL 6BG1 S/N		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	FAIR ・(Attn)	油漏れあり OIL LEAKING
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	FAIR ・(Attn)	効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	破れあり CUTS
Glasses	(FAIR)・ Attn	
AirCon	A/C ・ H/C ・(H only) ・ C only ・ None	
HYDRAULICS		
MAST Cylinder	(FAIR)・ Attn	
TILT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR ・ WORN ・ (UNEVEN WEAR)

COMMENT

E/G周り焦げ臭い AROUND ENGINE: BURNT SMELL

左ステアリングシリンダー傷あり LEFT STEERING CYLINDER: SCRATCHED

右ステアリングシリンダーにじみあり

RIGHT STEERING CYLINDER: OIL OOZING

ヒーター風出ない HEATER: NOT BLOWING AIR

*1 E/Gブロック周りにじみあり AROUND ENGINE BLOCK: OIL OOZING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。