

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|----------------|------|--------------------|--------|-----------|
| INSPECTION DATE | 2026/3/10 | MAKE | TADANO | MODEL | TR-160M-3 |
| SERIAL No. | PLATE : 525767 | | STAMP : TR162-0389 | | |
| HR METER | 28859 | HR | Odometer | 254735 | km |
| TIRE SIZE | 325/95R24 | | YEAR | YR | |

| | | |
|----------------------------------|---|-----------------------------------|
| ENGINE : MODEL | | S/N |
| Oil leakage | FAIR <input checked="" type="radio"/> Attn | E/G上部にじみあり UPPER PART: OIL OOZING |
| Blow-By | FAIR <input checked="" type="radio"/> Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | FAIR <input checked="" type="radio"/> Attn | |
| Oil | FAIR <input checked="" type="radio"/> Attn | |
| Exhaust Color | FAIR <input checked="" type="radio"/> Attn | |
| OPERATION PUMP | | |
| Sound | FAIR <input checked="" type="radio"/> Attn | |
| Oil leakage | FAIR <input checked="" type="radio"/> Attn | 油漏れあり OIL LEAKING |
| Power | FAIR <input checked="" type="radio"/> Attn | |
| COOLING SYSTEM | | |
| Radiator | FAIR <input checked="" type="radio"/> Attn | |
| Oil Cooler | FAIR <input checked="" type="radio"/> Attn | 油漏れあり OIL LEAKING |
| OPERATING SYSTEM | | |
| Computer | OK <input checked="" type="radio"/> NG | |
| Swing | FAIR <input checked="" type="radio"/> Attn | *1 |
| Travel | FAIR <input checked="" type="radio"/> Attn | リアステ不良 REAR STEERING: MALFUNCTION |
| TRANSMISSION | | |
| Transmission | FAIR <input checked="" type="radio"/> Attn | *2 |
| No. OF GEARS | 4 GEARS | |
| 4WD | 4WD <input checked="" type="radio"/> 6WD | |
| INTERIOR See Photos. 写真参照 | | |
| INTERIOR COND. | CLEAN · FAIR <input checked="" type="radio"/> DIRTY | |
| Operator's Seat | FAIR <input checked="" type="radio"/> Attn | 破れあり HUGE CUTS |
| Glasses | FAIR <input checked="" type="radio"/> Attn | |
| AirCon | A/C <input checked="" type="radio"/> H/C · H only · C only · None | |
| COMMENT | | |
| | | |

| | |
|--|--|
| BOOM | |
| No. of Section | 6 SECTIONS |
| CRACK/ENFORCEMENT | FAIR <input checked="" type="radio"/> Attn |
| DERRICKING CYL. | FAIR <input checked="" type="radio"/> Attn |
| EXTENSION CYL. | FAIR <input checked="" type="radio"/> Attn |
| JIB | YES <input checked="" type="radio"/> NO |
| JIB TYPE | STD <input checked="" type="radio"/> PWR |
| MAIN & SUB WIRE | YES <input checked="" type="radio"/> NO |
| FREE FALL | YES <input checked="" type="radio"/> NO |
| HOOK | 16t, BALL |
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED) | 4 |
| TIRE WEAR | FAIR <input checked="" type="radio"/> WORN · UNEVEN WEAR |
| COMMENT | |
| リアステアリングロックピン不良 REAR STEERING LOCK PIN: MALFUNCTION | |
| 左右Rステアリングシリンダー油漏れあり REAR STEERING CYLINDERS: OIL LEAKING | |
| OUTRIGGERS | |
| OUTRIGGERS | X · H <input checked="" type="radio"/> |
| OUTRIGGERS COND. | FAIR <input checked="" type="radio"/> Attn |
| Oil leakage (JACK CYL.) | FRONT L · R REAR L · R |
| Oil leakage (SLIDE CYL.) | FRONT L · R REAR L · R |
| COMMENT | |
| *1 ロータリージョイント油漏れあり SWING JOINT PART: OIL LEAKING | |
| *2 ミッションケース油漏れあり TRANSMISSION CASE: OIL LEAKING | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。