

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/3/10	MAKE	TADANO	MODEL	TR-100M-1
SERIAL No.	PLATE : FC0434		STAMP : TR100-0434		
HR METER	14830	HR	Odometer	134664	km
TIRE SIZE	11R22.5		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION	
Transmission	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1
No. OF GEARS	3 GEARS
4WD	<input checked="" type="radio"/> 4WD · 6WD
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn 破れあり CUT
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
COMMENT	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn 油漏れあり OIL LEAKING
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn にじみあり OIL Oozing
JIB	YES · <input checked="" type="radio"/> NO
JIB TYPE	STD · PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
FREE FALL	<input checked="" type="radio"/> YES · NO
HOOK	10t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	4
TIRE WEAR	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS	
OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
ウインチモーターソレノイド油漏れあり WINCH MOTOR SOLENOID: OIL LEAKING	
*1 トルクコンバーター油漏れあり TORQUE CONVERTER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。