

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/4/10	MAKE	YANMAR	MODEL	VIO20-3
SERIAL	32096B		STAMP	32096B	
HR METER	5306	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	250R	

<b>ENGINE : MODEL</b>		S/N	14481
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn	オイル量少ない ENGINE OIL LEVEL: NOT ENOUGH	
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	<u>YES</u> · NO		
<b>MAIN PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>OPERATING SYSTEM</b>			
Swing	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · <u>Attn</u> *1		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY		
Operator's Seat	<u>FAIR</u> · Attn	破れあり CUTS	
Glasses	<u>FAIR</u> · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
<b>BOOM / ARM / BKT</b>			
Boom	<u>FAIR</u> · Attn		
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn		
Arm Cylinder	<u>FAIR</u> · Attn		
ATTACHMENT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
<b>COMMENT</b>	
付属品: マット、パネル、ボルト FLOOR MAT, PANEL, & BOLTS AS SPARE	
*1 右足: 5cmくらい動いてロックする(前後5cmくらいずつしか動けない)	
*1 RIGHT TRACK: LOCKING TO MOVE (JUST ABLE TO TRAVEL FORWARD & BACKWARD BY ABOUT 5cm)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。