

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2026/3/26	MAKE	KOMATSU	MODEL	D51PX-22
SERIAL	B11486		STAMP	KMT0D080A51B11486	
HR METER	7937	HR	SHOE	710LGP	YEAR 2009 YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b>	<b>S/N</b>
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Blow-By <input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA <input checked="" type="radio"/> YES · NO	
<b>OPERATION PUMP</b>	
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Power <input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>	
Radiator <input checked="" type="radio"/> FAIR · Attn	
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE <input checked="" type="radio"/> PS · DD	DIFF. STEERING YES · <input checked="" type="radio"/> NO
Transmission <input checked="" type="radio"/> FAIR · Attn	
Travel <input checked="" type="radio"/> FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND. <input checked="" type="radio"/> CLEAN	FAIR · DIRTY
Operator's Seat <input checked="" type="radio"/> FAIR · Attn	
Glasses <input checked="" type="radio"/> FAIR · Attn	
AirCon A/C · <input checked="" type="radio"/> H/C	H only · C only · None
<b>BLADE &amp; CYLINDERS</b>	
BLADE <input checked="" type="radio"/> FAIR · Attn	
CYLD.(R) <input checked="" type="radio"/> FAIR · Attn	
CYLD.(L) <input checked="" type="radio"/> FAIR · Attn	
TILT CYLD <input checked="" type="radio"/> FAIR · Attn	
ANGLE CYLD <input checked="" type="radio"/> FAIR · Attn	

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
<b>COMMENT</b>			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper MULTI · S/S Shanks PCS  Ripper CYLD. FAIR · Attn </div>			
<b>COMMENT</b>			
リペイントあり REPAINTED			
シフトアップボタン戻り悪い SHIFT-UP BUTTON: HARD TO RETURN			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) </div>			
			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。