INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/4/1	MAKE	CAT	MODEL	950G
SERIAL	5MW00759		STAMP	5MW00759	
HR METER	17482 HR	Odometer	– km	YEAR	YR
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	23.5-25	

ENGINE : MODEL	S/N	
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	(FAIR)・ Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	
Glasses	FAIR ・(Attn)	F正面、左側割れあり WINDSHIELD: CRACKED
AirCon	A/C ・ (H/C) ・ H only ・ C only ・ None	
FRONT & CYLINDERS		
Arm	(FAIR)・ Attn	
Bell crank	(FAIR)・ Attn	
Bucket	(FAIR)・ Attn	
Articulate	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
TIRE WEAR	(FAIR) ・WORN ・ UNEVEN WEAR		
COMMENT			
ミッション下油漏れあり BOTTOM OF TRANSMISSION: OIL LEAKING			
STEERING TYPE	(WHEEL STEERING) / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	YES ・ (NO)		
ATTACHMENTS			
STD BKT	(YES)・ OTHER		
BLADE	YES ・ (NO)	Piping for Tilt	YES ・ (NO)
COMMENT			
右サイドカバー欠 RIGHT SIDE COVER: MISSING			
*1 ブロック周り油漏れあり AROUND ENGINE BLOCK: OIL LEAKING			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。