

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/3/13	MAKE	KOMATSU	MODEL	D375A-2
SERIAL	16206		STAMP	NOT FOUND	
HR METER	9474	HR	SHOE	700G	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL	S/N
Oil leakage (FAIR) · Attn	
Blow-By (FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound (FAIR) · Attn	
Oil (FAIR) · Attn	
Exhaust Color (FAIR) · Attn	
US EPA	YES · (NO)
OPERATION PUMP	
Sound (FAIR) · Attn	
Oil leakage (FAIR) · Attn	
Power (FAIR) · Attn	
COOLING SYSTEM	
Radiator (FAIR) · Attn	
Oil Cooler (FAIR) · Attn	
TRANSMISSION & TRAVEL	
T/M TYPE (PS) · DD	DIFF. STEERING YES · (NO)
Transmission (FAIR) · Attn	
Travel (FAIR) · Attn	
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY
Operator's Seat (FAIR) · Attn	
Glasses (FAIR) · Attn	
AirCon	A/C · (H/C) · H only · C only · None
BLADE & CYLINDERS	
BLADE (FAIR) · Attn	
CYLD.(R) (FAIR) · Attn	
CYLD.(L) (FAIR) · Attn	
TILT CYLD (FAIR) · Attn	
ANGLE CYLD (FAIR) · Attn	

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Ripper (MULTI) · S/S	Shanks 2 PCS
Ripper CYLD. (FAIR) · Attn	
COMMENT	
ヒーター&クーラー風出ない HEATER & COOLER: NOT BLOWING AIR	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。