

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2026/3/18	MAKE	CAT	MODEL	D6TLGP
SERIAL	CAT00D6TPSGT00283			STAMP	CAT00D6TPSGT00283
HR METER	4024	HR	SHOE	1000LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b> C9.3		<b>S/N</b> SYE09569	
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	(YES) · NO		
<b>OPERATION PUMP</b>			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
<b>COOLING SYSTEM</b>			
Radiator	(FAIR) · Attn		
Oil Cooler	(FAIR) · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	(PS) · DD	DIFF. STEERING	(YES) · NO
Transmission	(FAIR) · Attn		
Travel	(FAIR) · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	(FAIR) · Attn		
Glasses	(FAIR) · Attn		
AirCon	(A/C) · H/C · H only · C only · None		
<b>BLADE &amp; CYLINDERS</b>			
BLADE	(FAIR) · Attn		
CYLD.(R)	(FAIR) · Attn		
CYLD.(L)	(FAIR) · Attn		
TILT CYLD	(FAIR) · Attn		
ANGLE CYLD	FAIR · Attn		

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
<b>COMMENT</b>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	(FAIR) · Attn		
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。