INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2026/3/26	CATEGORY	(TRUCK CRANE) / ALL TERRAIN CRANE		
MAKE	SUMITOMO	MODEL	HC-218S		
SERIAL	HC218-0329	STAMP	NOT FOUND		
HR METER	2873 / CRANE: 270 HR	Odometer	2572 km	YEAR	YR
CHASSIS	MODEL P-KG55V	No.	00003	TIRE	14.00-20 20PR

ENGINE(CRANE) : MODEL		S/N 531132
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	

ENGINE(CHASSIS) : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	

OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	

COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	

OPERATING SYSTEM		
Computer	OK · NG	未確認 NOT CHECKED
Swing	FAIR · (Attn)	未確認 NOT CHECKED
Travel	FAIR · (Attn)	未確認 NOT CHECKED

TRANSMISSION & TRAVEL				
T/M TYPE	AT · (MT)		No. OF GEARS	7 GEARS
Transmission	(FAIR) · Attn			
No. of DRIVE WHEELS	2 WD			
Travel	(FAIR) · Attn			
FOOT BRAKE	(FAIR) · Attn			
PARKING BRAKE	(FAIR) · Attn			

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	A/C · H/C · H only · C only · (NONE)	

CRANE		
WEIGHT	1	
HOOK	80t, 25t, 15t, 8t	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m×1, 6m×2, 3m×1	
BOOM TOTAL	36m	
No. of Section	- SECTIONS	
TOP SHEAVE	YES · (NO)	
JIB	STD · PWR	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR	

COMMENT

OUTRIGGERS		
OUTRIGGERS	FAIR · (Attn)	未確認 OPERATION: NOT CHECKED
FRONT JACK	(YES) · NO	

COMMENT

ブームたまに動かなくなる BOOM: OCCASIONALLY NOT MOVING

@SAKURA YARD

BOOM: TOP, BOTTOM, 9m×1, 6m×2, 3m×1

HOOK: 80t, 25t, 15t, 8t

WEIGHT×1

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。