

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/3/27	MAKE	KATO	MODEL	KR-70H-L
SERIAL No.	PLATE : 5210090		STAMP : KRC006-0090		
HR METER	22337	HR	Odometer	53092	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION		
Transmission	<input checked="" type="radio"/> FAIR · Attn	*1
No. OF GEARS	4 GEARS	
4WD	4WD	<input checked="" type="radio"/> 6WD
INTERIOR See Photos. 写真参照		
INTERIOR COND.	<input checked="" type="radio"/> CLEAN · FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
COMMENT		

BOOM			
No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn		
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn		
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn		
JIB	<input checked="" type="radio"/> YES · NO		
JIB TYPE	STD	<input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO		
FREE FALL	YES	<input checked="" type="radio"/> NO	
HOOK	70t, 34t, BALL, HANGER		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)			4
TIRE WEAR		<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR	
COMMENT			
OUTRIGGERS			
OUTRIGGERS	X	<input checked="" type="radio"/> H	
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
*1 トルコンにじみあり TORQUE CONVERTER: OIL OOZING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。